

SOUTH PRODUCTION NOTES

Oct 21, 2015
7-3 Shift notes

BASF EMPLOYEES

30 Last Recordable
30 Last Lost Time

SAFETY Notes: Strains and Sprains are the most common workplace injury. Take time to loosen up before starting a job.

Safety Meetings will be this week. B-shift at 1:30 in conf-B

Title V Notes: Extra effort needed to keep an eye on Trimer as we are running 4601. PLEASE watch stack, monitor suction at HMI display for pfadler, and maintain proper chem tank make-up. GO SLOW AND BE SAFE!!!!

#1 MED / AI 5637:

On hold until we get the calciner back up and running.

#1 RC / AI 5637:

On hold until we get the trimer back (currently being used for the D-4601).

#2 MED line / Cu 0560:

Kristen would like us to hold for calcined results, she is unsure of the crush strength of the material due to the additional water we have added to the batches. Gem worked on the discharge valve and told us that it is good to run.

#2 RC/ Cu 0560:

Continue. **MAKE SURE TO FEED IN BAG ORDER AND TO FILL OUT THE LOG SHEET FOR WHAT IS BEING FED TO THE CALCINER.**

Make sure that we do not feed the bag marked hold for Kristen.

#3 MED line / AI 4126 next:

Holding for engineering, will start making batches on Wednesday morning.

Spiral elevator has been temp fixed, and permanent repairs will need to be scheduled before next run.

End seals will need greased once a shift.

#3 RC / AI 4126 next:

Sand has been run through the calciner. Screener changed over. Calciner lit.

#4 RC / D 0222 done:

Down, Began cleaning on midnight shift. Continue. Clean up sheet on GL desk.

#5 RC / Hold for refractory repair:

Cleaning is ongoing, area roped off from earlier work

The Feed end rotolock has been dropped so that we can clean it out (it was clogged with material).

New cartridges for the Discharge end vacumax are now in the store room.

Please sign out when taking.

Need a WO to reinstall feed end rotolock.

WOW for the 5A blowdowns again. They are still not working well

#6 RC & Dryer / D 0720 LAQ:

Restarted feed on midnight shift. Got burners 5 and 12 turned back on. Continue.

Exhaust to the Sly only. CTO not needed for this product.

West Pfaudler / 4601

Starting the drying of the 2nd impreg on midnight shift. On a 6 hour hold then can start taking LOL's.

On the new panel-view, Kirk has added a pfaudler lid pressure average in the upper left corner. It is not really giving us a good number as to the pressure in the pfaudler.

East Pfaudler/ D 0720 LAQ:

Continue making batches. Batch in the hopper will be ready to feed at 8:30

6 Tank: Tank empty

7 Tank: Cleaned and rinsed

National Dryer / Clean.

Hold

PK Blender - hold:

PK has been washed out.

Floor has been washed down.

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down.

Gauge should be reset at 3.5 and 4.25

Abbe Blender: D 5206 is next

After walk through on Sunday morning, Abbe looks ready. Can start up as man power allows.

HF CD is on Andrew's desk.

Operators may need a refresher on HF and procedures for running 5206.

Tower 3 / QVAM next:

Hold off on unloading until day shift when EH & S can be involved in testing. Drum Levelling still needs to be completed.

Tower 6 / DPT 101:

running

Need to have Kirk troubleshoot when tower is under H2.

Cu-0860 repacking in screening room:

Pendant for the dumper is having issues cutting in and out. A work order was written on second shift. **Was this fixed??**

Continue with inspection and repacking/repainting of lots 341-349 and 363-369. Work on this if other jobs done or down.

Be certain that every drum completed is logged.

Steam heater was turned on in screening room.

North Screener / DPT-0101:

Done.

South Screener / DPT-0101:

Done.

#2662 (west) Pill Machine /

Back together and holding

#2664 (east) Pill Machine /

Back together and holding

TK #2 / down:

Unloaded all cars for refractory repairs.

TK #4 / Cu 0540:

Continue loading and unloading.

Milling V 2046:

Dumper gasket repairs have been completed. Continue milling drums.

Harrop Kiln / AI 3920:

All material is finished. Need to evaluate if we can rebuild the cars while it is down.

Building 27 Belt Filter / Cu 6081:

Continue with strikes. Had issues keeping the north glycol pump running. Currently Switch over to the south. WOW.

-When receiving Copper nitrate from the North end, it will be necessary to have the suction at -5 or more on the scrubber to tanks 109/110 in order for the North end to get their prompt to send the solution. This means we will need to choke back the suction to tank two in order to get enough suction to trigger the interlock.

PRODUCTION PRIORITIES:

- 1) #6RC/East Pfaudler/CTO**
- 2) West Pfaudler/Trimer**
- 3) South Precip/Dry**
- 4) #4 RC for the D-0222 bag re-fire (this may be done by now)**
- 5) #2 MED/#2RC**
- 6) Reduction Towers**
- 7) V-2046 Milling/Mill/Dust Collector/Dumper**
- 8) #3 MED/#3RC**
- 9) #2 RC North**
- 10) #1 MED/#1RC**
- 11) North PK/Wyssmont**